Declass Review by NIMA / DoD

13 June 1963

MEMORANDUM FOR: Chief. Technical Intelligence Division

SUBJECT:

Comparator Readout Equipment

PROBLEM:

Replacement or repair of readout equipment to service the various comparators in TAB.

STATEMENT OF FACTS:

1. Telecordex-flexowriter equipment now in use with the comparators requires replacement or overhaul to maintain reliability of output.

25X1A

2. Additional equipment must be secured to service the new comparator being purchased.

25X1A

25X1A

25X1A

readout equipment for the 3. Reliability of the three RIC-1 comparators is undependable and may require replacement with more reliable equipment.

six channel code currently in use should be replaced by the seven channel field data code (a more universal code compatable with the 490 input format) as soon as possible.

DISCUSSION:

- 1. Basically, the telecordex is reliable and with proper maintenance and periodic replacement of all tubes it should provide dependable service. A complete set of replacement tubes have been ordered at a cost of around for three instruments.
- A new instrument could be purchased to replace the telecordex, such as the solid state version of the telecordex or the pigmi. A replacement instrument would cost about
- 3. The chief sources of trouble in the readout cycle is the flexowriter. A separate tape punch and IBM typewriter is a possible alternate for the flexowriter. The purchase of a spare flexowriter or two would

25X1A

25X1A

25X1A

downgrading and declassification

Approved For Release 2002/01/02 : CIA-RDP78B04747A000900040016-2

provide backup in case of a flexowriter break down. The spare could be used while the malfunctioning flexowriter is undergoing repairs. Flexowriters cost approximately

25X1A

4. As additional comparators are acquired additional readout equipment is needed. There is also the problem of replacing the readout equipment of the RIC-ls with more reliable instruments. Should these instruments be of a new design or should they be more telecordexes? There is merit in having one common instrument allowing for interchangability as well as stocking of parts and simplicity of maintenance.

RECOMMENDATIONS:

25X1A

25X1A

- 1. That the current telecordex instruments be retained and a complete set of tubes periodically installed.
- 2. That an improved readout instrument be selected and purchased as additional equipment is needed.
- 3. That new tape punch and hard copy printout equipment be purchased to replace the flexowriters. This same equipment also be used with the improved readout instrument selected. This equipment to be designed to produce the seven channel field data code.

25X1A

Deputy Chief
Technical Intelligence Division

Distribution:

Orig & 1 - Chief, TID

1 - TAB

1 - CB

1 - Chrono

NPIC/TID:

Jlh/2955

NPIC ROUTING SLIP

Approved For Release 2002/01/02 : CIA-RDP78B04747A000990040016-2 FOR YOUR INITIALS DATE то DIR DEP/DIR EXEC/DIR ASST FOR OPS ASST FOR ADMIN ASST FOR P&D CH/CSD D CH/PD CH/TID STATINTL SIO/CIA (PID) SIO/ARMY SIO/NAVY SIO/AF LO/DIA LO/NSA Approprent or manage 200 200 100 this approach to the protein.

Approprent or manage 200 200 100 this approach. PSD (OVER)

STATINTL

STATINTL

SYM ZONE DESCRIPTION	DATE	APPROVAL

Notes:

25X1A

- 1. Model TMP-200 Tapemaker Printer with the following:
 - a) Special code 7 level field data code.
 - b) Pin feed or tractor feed.
 - c) Parity generator.
- 2. Optional Equipment:
 - a) 113A Remote constants switches 4 to be used at operator's station.
 - b) 106A remote Nixie display 6 digit plus sine for both X and Y axis, includes filter windows.
- 3. One set of manuals required.

STATINTL

DF BY		John St. And tend tend tend tend tend tend tend te
HK BY APPD		
BY		SYSTEM BLOCK DIAGRAM
		AIR FORCE Hist. T.
NEXT ASSY	ed For Release 20 USED ON	02/01/02 PCIA-RDP78B04747A000900040016-2 MJO:

STATOTHR

Next 12 Page(s) In Document Exempt